

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
DIVISION OF HAZARDOUS WASTE REMEDIATION
INACTIVE HAZARDOUS WASTE DISPOSAL REPORT

CLASSIFICATION CODE: 2

REGION: 8

SITE CODE: 828021
EPA ID: NYD980780753

NAME OF SITE: Golden Road Disposal Site
STREET ADDRESS: Golden Road

TOWN/CITY: Child
COUNTY: Monroe

ZIP: 14624

SITE TYPE: Open Dump- X Structure- Lagoon- Landfill- Treatment Pond-
ESTIMATED SIZE: 8 Acres

SITE OWNER/OPERATOR INFORMATION:

CURRENT OWNER NAME: Howard Fitzsimmons, Sr.
CURRENT OWNER ADDRESS: 227 Golden Rd., Rochester, NY
OWNER(S) DURING USE: Howard Fitzsimmons, Sr.
OPERATOR DURING USE:
OPERATOR ADDRESS:
PERIOD ASSOCIATED WITH HAZARDOUS WASTE: From 1955 To 1976

SITE DESCRIPTION:

Lat. 43 07'11.6"N Long. 77 45'38.9"W
Flat topography Residential area; nearest house approx. 400 feet
Nearest waterbody: Intermitent stream flows to a pond located near Rte. 490. Wetlands are to the SE & SW
Nearest water supply: Private well (Fitzsimmons) Approx. 500 feet away

This site was identified thru a nuisance complaint received by the Monroe County Sheriff's Office. The site is physically divided by the Central Railroad tracks. It was inspected and sampled on July 20, 1983. During the inspection about 200 drums in various stages of decay were noted at two locations on the south side of the tracks. Fly ash and foundry sand were exposed on the south side of the tracks as well. The surficial cleanup of the site was completed on June 27, 1985. A total of 562 drums and containers and 75 cubic yards of contaminated soil and debris were removed from the site for a cost of approximately \$59,700. A final draft Phase II investigation report has been prepared for this site. Groundwater analysis indicated elevated levels of heavy metals and low levels of volatile organics.

HAZARDOUS WASTE DISPOSED: TYPE	Confirmed-X	Suspected- QUANTITY (units)
Oily wastes		200+ drums; most are
Ink wastes, Solvents, PCB's		corroded and rusted.
Fly ash		unknown
Unknown buried wastes		unknown



SITE CODE: 828021

ANALYTICAL DATA AVAILABLE:

Air- Surface Water- Groundwater-X Soil-X Sediment-

CONTRAVENTION OF STANDARDS:

Groundwater- Drinking Water- Surface Water- Air-

LEGAL ACTION:

TYPE.: None State-
STATUS: Negotiation in Progress- Order Signed-

REMEDIAL ACTION:

Proposed- Under design- In Progress- Completed-X
NATURE OF ACTION: Removal of drums and surficial soil and debris.

GEOTECHNICAL INFORMATION:

SOIL TYPE: Shallow muck
GROUNDWATER DEPTH: High seasonal water table

ASSESSMENT OF ENVIRONMENTAL PROBLEMS:

Further investigation is necessary to assess any environmental problems.

ASSESSMENT OF HEALTH PROBLEMS:

The most likely sources of the contamination at this site include foundry sands, fly ash and dried paint residue. Approximately five hundred drums were removed from the site in 1985. A major concern is the reported disposal of artillery shells from the U.S. Army Reserve. To date it has not been possible to determine if the shells are spent or remain live. Chemical contaminants include benzene, toluene, xylenes, organic dyes, cadmium and lead. Public water is available, but groundwater is a concern since some residents use it as a source of drinking water. DOH and MCHD sampled private wells located near the site. One sample contained trichloroethene at a concentration below DOH Part 5-1 drinking water standards. No other samples collected exhibited any evidence of an impact from the site. Vehicular traffic into the site is restricted.

